



1965-68 Mustang Fire Extinguisher Mount Bracket

C5ZZ-FIREX-MNT

Part Number: C5ZZ-FIREX-MNT

Thank you for purchasing a quality Scott Drake product. Please refer to the installation instructions below when installing this product.





Photo 1





Photo 2





- Screwdriver
- Masking Tape
- Hole punch
- Hammer
- · Permanent marker
- Electric Drill
- 1/8 and 5/16 drill bits
- Ulility knife or scissors
- Torque wrench














Step 6 Center punch holes as shown. See Photo 5.



Photo 3



Photo 4



Photo 5



- Step 7 Drill 1/8" pilot holes through one layer of sheet metal. Increase drill size incrementally until drilling final hole size of 5/16". If screws are hard to start, it may be necessary to drill slightly larger. File sharp edges of holes. See Photo 6.
- Step 8 Place bracket over holes and install sheet metal screws provided. Snug bracket to floor pan. See Photo 7.
- Step 9 Temporarily reinstall seat and check location of bracket. It will be beneficial to reinstall extinguisher and quick release bracket if removed. See Photo 8.
- Step 10 Adjust location as necessary. Remove seat and tighten sheet metal screws. See Photo 9.
- Step 11 Cut carpet as needed to overlay mounting bracket. See Photos 10 & 11.
- Step 12 Reinstall seat, torqueing screws to factory spec.



Completed Installation of Scott Drakes 1965-68 Mustang Fire Extinguisher Mount Bracket

SATISFACTION GUARENTEED

If you are not happy with this product, for any reason, or found product to be defective in manufacturing, simply return it to Scott Drake within 30 days of purchase and we will replace it - no questions asked. We stand behind our products one hundred percent, so you can sit behind the wheel with pride.

*Proof of purchase and dated reciept must be present with any return. All returned products are tested and if found to be damaged by the installer, no replacement will be issued. You pay the cost to ship to us, we pay for the return shipping. Guarantee does not include any labor and/or tax charges incurred.



Photo 6



Photo '





Photo 9



Photo 10